

# Spot the Hazard.

Can you spot the hazards?



Image 995: OSHA Training Institute, Southwest Education Center <http://www.elcosh.org>

- Hazards
- Scaffold overloaded (correct scaffold for the load, planking sags more than 1/60 of span)
- Load is not on top of supports
- Scaffold missing: cross bracing, full planking, falling object protection
- No working space
- Scaffold not level (leaning)



**Safety Pays.  
Falls Cost.**

[stopconstructionfalls.com](http://stopconstructionfalls.com)